



PIANC Report No. WG165

## Design and Maintenance of Container Terminal Pavements

Report Date: 2015

Revision No. (n/a)

### Corrigenda Sheet\_v1.0

Page No.	Section No.	Comment	Amendment
53	Section 8.4	Formula 15. Dimensionless coefficient 2.78 omitted in error.	Formula 15 should read $Q = 2.78 \times C \times l \times A$
117	Appendix 2	Isaac Wingfield was omitted in error from the list of Working Group members	Insert:  <b>Member:</b> Isaac WINGFIELD Deputy Practice Lead South-East USA Ports and Marine, Hatch Infrastructure Hatch 3611 Queen Palm Dr. Suite 100 Tampa Florida 33619 USA Tel: +1 904 233 6501 <a href="mailto:Isaac.Wingfield@hatch.com">E-mail: Isaac.Wingfield@hatch.com</a>